



ABN: 91 263 924 893
QLD LIC: PMTO-14604
NSW LIC: 5072691
QBCC LIC: 1191024

CHRIS SANDS: 0414 324 448
info@allianceinspections.com.au
www.allianceinspections.com.au
PO Box 963 Palm Beach QLD 4221



CLIENT: Nikki Smith

CLIENT ADDRESS: 2/22 Hastings Road, Bogangar

PROPERTY INSPECTED ADDRESS: 2/22 Hastings Road, Bogangar

INSPECTION DATE: 24th May, 2024

EMAIL: Nikjsmith@outlook.com

PHONE:

MOBILE: 0423 578 351

INVOICE: 1667

Contents:

Special conditions or instructions	Section F - Risk management options
Section A - Results of inspection - summary	Section G - Additional comments
Section B - General	Section H - Annexures to this report
Section C - Accessibility	Section I - Certification
Section D - Significant items	Definitions to help you better understand this report
Section E - Conclusion	Terms on which this report was prepared

If you have any queries with this report or require further information, please do not hesitate to contact the person who carried out the inspection. This Report contains reference to material that is copyright Standards Australia. That content is reproduced with permission from SAI Global under copyright Licence 1010-c026.

Special conditions or instructions:

There are no special conditions or instructions.

Section A: Results of inspection - summary

This Summary is not the Report. The following Report MUST be read in full in conjunction with this Summary. If there is a discrepancy between the information provided in this Summary and that contained within the body of the Report, the information in the body of the Report shall override this Summary.

In respect of significant items:

Evidence of active (live) termites	was not found.
Evidence of termite activity (including workings) and/or damage	was not found.
Evidence of a possible previous termite management program	was not found.
The next inspection to help detect any future termite attack is recommended in:	6 months
Evidence of chemical delignification damage	was not found.
Evidence of fungal decay activity and/or damage	was found - See Item D7
Evidence of wood borer activity and/or damage	was not found.
Evidence of conditions conducive to timber pest attack	was found - see Item D9-13
Evidence of major safety hazards	was not found.

Due to the level of accessibility for inspection including the presence of obstructions, the overall degree of risk of undetected timber pest attack and conditions conducive to timber pest attack was considered High - see Section C.

A further inspection is strongly recommended of those areas that were not readily accessible and of inaccessible or obstructed areas once access has been provided or the obstruction removed. This will involve a separate visit to the site, permission from the owner of the property and additional cost. For further information or advice see Section C "Accessibility".

Unless stated otherwise, any recommendation or advice given in this Report should be implemented as a matter of urgency. For further information including advice on how to help protect against financial loss due to timber pest attack see Section F.

Section B: General

Building type:	Triplex
Number of storeys:	Multi Storey
Main building - floor construction:	Concrete slab & Suspended timber framed floor
Main building - wall construction:	Cavity brick/brick veneer & cladding
Main building - roof construction:	Timber framed
Other (timber) building elements:	Various interior fixout trims & accent timbers, Cabinetry, Landscaping materials and/or fences/screens, Decking,
Occupancy status:	Unoccupied but partly furnished
Orientation (main entrance):	The garage faces west

Please Note: Orientation is only provided as a reference to locate points of interest, or issues relating to the structure, and may not be an accurate description of the aspect of the building.

Prevailing weather conditions at the time: Dry

Section C: Accessibility

Areas inspected:

The inspection covered the Readily Accessible Areas of the Building and Site including: building interior, building exterior, roof space, site

Areas not inspected:

The inspection did not include areas, which were inaccessible, not readily accessible or obstructed at the time of inspection. The Consultant did not move or remove any obstructions which may be concealing evidence of defects including timber pest attack. Areas, which are not normally accessible, were not inspected such as under slabs on ground as it is not "considered practical" to gain access to them. Evidence of timber pest attack in obstructed or concealed areas may only be revealed when the items are moved or removed or access has been provided.

Strata or company title properties:

The Inspection was limited to assessing the interior and immediate exterior of the unit. The Client may have additional liability for timber pest attack in the common property.

Obstructions:


The following may conceal timber pest attack:

Building Interior: wall linings, ceiling linings, floor coverings, window furnishings, cabinetry

Building Exterior: hot water unit, gates & fences, decking, render/texture coating, adjacent dwellings & common property, gas storage cylinders, hot water unit enclosure

Roof Space: low pitched and boxed in areas in roof space, insulated sarking, stored goods

Site: vegetation and/or foliage limits inspection to areas of site







Inaccessible areas:

All areas permitted entry

Undetected timber pest risk assessment:

Due to the level of accessibility for inspection including the presence of obstructions, the overall degree of risk of undetected timber pest attack and conditions conducive to timber pest attack was considered: High

A further inspection is strongly recommended of areas that were not readily accessible, and of inaccessible or obstructed areas once access has been provided or the obstruction removed. This may require the moving, lifting or removal of obstructions such as floor coverings, furniture, stored items foliage and insulation. In some instances, it may also require the removal of ceiling and wall linings, and the cutting of traps and access holes. For further advice consult the person who carried out this report.

Section D: Significant items

The following items were reported on in accordance with the Scope of Inspection.

Timber pest attack:

Evidence of timber pest activity and/or timber pest damage:

D1 Active (live) termites - include the location, the genus and where practical the species involved and its potential to cause significant structural damage and whether a nest was or was not found

No evidence was found.

Important Note. As a delay may exist between the time of an attack and the appearance of telltale signs associated with an attack, it is possible that termite activity and damage exists though not discernible at the time of inspection.

D2 Subterranean termite management proposal

A proposal is recommended. The installation of a termite management system is recommended to help protect this building from undetected termite attack.

Please Note: Where a termite barrier or termite management system exists at the property, all works and materials are presumed to have been installed to the manufacturers specifications, however, we are unable to verify that the system has been installed and maintained as required, or has not been damaged/disturbed during the construction/installation. In all cases where a termite management system exists, we still recommended the installation of a termite management system to help further protect the property from undetected termite attack.

D3 Termite workings and/or damage

No evidence was found.

D4 Previous termite management program

No evidence was found

All certification and paperwork regarding all termite management on this property should be obtained for our assessment.

D5 Frequency of future inspections

The next inspection to help detect termite attack is recommended in: 6 months

Important Note. Australian Standard AS 3660 recognises that regular inspections will not prevent termite attack, but may help in the detection of termite activity. Early detection will allow remedial treatment to be commenced sooner and damage to be minimised.

D6 Chemical delignification

No evidence was found.

D7 Fungal decay

The following evidence was found:

At time of inspection fungal decay was located in, but not necessarily limited to: upper level rear deck beam and to fencing timbers at rear.

Removal/replacement of the affected timbers is recommended.



D8 Wood borers

No evidence was found.

Conditions conducive to timber pest attack:

The Consultant sought evidence of noticeable building deficiencies or environmental factors that may contribute to the presence of timber pests. In respect of moisture management issues, the inspection included the potential for or presence of water or dampness in unintended locations.

D9 Lack of adequate subfloor ventilation


Not applicable due to construction design.

D10 The presence of excessive moisture

The following evidence was found:

At time of inspection elevated moisture readings were located in, but not necessarily limited to the: interior garage wall linings adjacent to the garage door

The wall lining appears to be gyprock affixed directly to brickwork.



The presence of moisture stains

Further inspection to these areas is recommended to locate and rectify the source of the moisture.

D11 Bridging or breaching of termite barriers and inspection zones

The following evidence was found:

The visual inspection zone was bridged by the adjacent dwellings &/or common property the garage door jamb timbers on ground floor and by the hot water unit enclosure.

The visual inspection zone was concealed, or partially concealed by the adjacent dwellings &/or common property, and by the dividing fences.

Adjustment of the above items is recommended to prevent bridging the visual inspection zone and to provide a minimum of 75mm clearance to this area.





D12 Untreated or non-durable timber used in a hazardous environment

The following evidence was found:

All timber items in ground contact, including but not necessarily limited to: Timber fences


These items should be adjusted to provide a minimum of 75mm ground clearance, or replaced with termite and decay resistant materials.



D13 Other conditions conducive to timber pest attack

The following evidence was found:

- All timber items in ground contact including but not necessarily limited to timber fences, landscaping and retaining wall timbers should be adjusted to provide a minimum of 75mm ground clearance or replaced with termite and decay resistant materials.
- the hot water unit overflow drain should be unblocked to prevent moisture buildup against the structure.



Major safety hazards:

The Consultant sought evidence of any item or matter (within the Consultant's expertise) that may constitute a present or imminent major safety hazard. For example, evidence of the imminent collapse of a structural member and other building elements made unsafe by timber pest attack.

D14 Major safety hazards

No evidence was found.

Section E: Conclusion

The following Timber Pest remediation actions are recommended:

1. No Treatment of Timber Pest Attack is required
2. In addition to this Report a Subterranean Termite Management Proposal to help manage the risk of future subterranean termite access to buildings and structures is recommended - see Item D2
3. Yes, as detailed in Section D. removal of Conditions Conducive to Timber Pest Attack is necessary.
4. Due to the susceptibility of the property to the sustaining Timber Pest Attack the next inspection is recommended in 6 months.

Your attention is drawn to the advice contained in the Terms & Conditions of this Report including any special conditions or instructions that need to be considered in relation to this Report.

Section F: Risk management options

To help protect against financial loss, it is essential that the building owner immediately control or rectify any evidence of destructive timber pest activity or damage identified in this Report. The Client should further investigate any high risk area where access was not gained. It is strongly advised that appropriate steps be taken to remove, rectify or monitor any evidence of conditions conducive to timber pest attack.

It is recommended that the client act on the following advice to further protect their investment against timber pest infestation:

Undertake thorough regular inspections at intervals not exceeding twelve months or more frequent inspections where the risk of timber pest attack is high or the building type is susceptible to attack. To further reduce the risk of subterranean termite attack, implement a management program in accordance with Australian Standard AS 3660. This may include the installation of a monitoring and/or baiting system, or chemical and/or physical barrier. However, AS 3660 stresses that subterranean termites can bridge or breach barrier systems and inspection zones and that thorough regular inspections of the building are necessary.

If the Client has any queries or concerns regarding this Report, or the Client requires further information on a risk management program, please do not hesitate to contact the person who carried out this Inspection.

Section G: Additional comments

Section H: Annexures to this report

There are no annexures attached.

Section I: Certification

This document certifies that the property described in this Report has been inspected by the Timber Pest Detection Consultant in accordance with the level of service requested by the Client and the Terms and Conditions set out in this Report, and in accordance with the current edition of the Report Systems Australia (RSA) Handbook Timber Pest Detection Reports 'Uniform Inspection Guidelines for Timber Pest Detection Consultants'.

Authorised Signatory:

Definitions to help you better understand this report

"Timber Pest Attack" Timber Pest Activity and/or Timber Pest Damage.

"Timber Pest Activity" Telltale signs associated with 'active' (live) and/or 'inactive' (absence of live) Timber Pests at the time of inspection.

"Timber Pest Damage" Noticeable impairments to the integrity of timber and other susceptible materials resulting from attack by Timber Pests.

"Major Safety Hazard" Any item that may constitute an immediate or imminent risk to life, health or property resulting directly from Timber Pest Attack. Occupational, health and safety or any other consequence of these hazards has not been assessed.

"Conditions Conducive to Timber Pest Attack" Noticeable building deficiencies or environmental factors that may contribute to the presence of Timber Pests.

"Readily Accessible Areas" Areas which can be easily and safely inspected without injury to person or property, are up to 3.6 metres above ground or floor levels or accessible from a 3.6 metre ladder, in roof spaces where the minimum area of accessibility is not less than 600 mm high by 600 mm wide and subfloor spaces where the minimum area of accessibility is not less than 400 mm high by 600 mm wide, providing the spaces or areas permit entry. The term 'readily accessible' also includes:

- (a) accessible subfloor areas on a sloping site where the minimum clearance is not less than 150 mm high, provided that the areas is not more than 2 metres from a point with conforming clearance (i.e. 400 mm high by 600 mm wide); and
- (b) areas at the eaves of accessible roof spaces that are within the consultant's unobstructed line of sight and within arm's length from a point with conforming clearance (i.e. 600 mm high by 600 mm wide).

"Client" The person or persons for whom the Timber Pest Report was carried out or their Principal (i.e. the person or persons for whom the report was being obtained).

"Timber Pest Detection Consultant" A person who meets the minimum skills requirement set out in the current Australian Standard AS 4349.3 Inspections of Buildings. Part 3: Timber Pest Inspection Reports or state/territory legislation requirements beyond this Standard, where applicable.

"Building and Site" The main building (or main buildings in the case of a building complex) and all timber structures (such as outbuildings, landscaping, retaining walls, fences, bridges, trees and stumps with a diameter greater than 100 mm and timber embedded in soil) and the land within the property boundaries up to a distance of 50 metres from the main building(s).

"Timber Pests" One or more of the following wood destroying agents which attack timber in service and affect its structural properties:

- (a) *Chemical Delignification* - the breakdown of timber through chemical action.
- (b) *Fungal Decay* - the microbiological degradation of timber caused by soft rot fungi and decay fungi, but does not include mould, which is a type of fungus that does not structurally damage wood.
- (c) *Wood Borers* - wood destroying insects belonging to the order 'Coleoptera' which commonly attack seasoned timber.
- (d) *Termites* - wood destroying insects belonging to the order 'Isoptera' which commonly attack seasoned timber.

"Tests" Additional attention to the visual examination was given to those accessible areas which the consultant's experience has shown to be particularly susceptible to attack by Timber Pests. Instrument Testing of those areas and other visible accessible timbers/materials/areas showing evidence of attack was performed

"Instrument Testing" Where appropriate the carrying out of Tests using the following techniques and instruments:

- (a) electronic moisture detecting meter - an instrument used for assessing the moisture content of building elements;
- (b) stethoscope - an instrument used to hear sounds made by termites within building elements;
- (c) probing - a technique where timber and other materials/areas are penetrated with a sharp instrument (e.g. bradawl or pocket knife), but does not include probing of decorative timbers or finishes, or the drilling of timber and trees; and
- (d) sounding - a technique where timber is tapped with a solid object.

"Subterranean Termite Management Proposal" A written proposal in accordance with Australian Standard AS 3660.2 to treat a known subterranean termite infestation and/or manage the risk of concealed subterranean termite access to buildings and structures.

Terms on which this report was prepared

SERVICE As requested by the Client, the inspection carried out by the Timber Pest Detection Consultant ("theConsultant") was a

PURPOSE The purpose of this inspection is to assist the Client to identify and understand any Timber Pest issues observed at the time of inspection.

SCOPE OF INSPECTION This Report only deals with the detection or non detection of Timber Pest Attack and Conditions Conducive to Timber Pest Attack discernable at the time of inspection. The inspection was limited to the Readily Accessible Areas of the Building & Site and was based on a visual examination of surface work (excluding furniture and stored items), and the carrying out of Tests.

ACCEPTANCE CRITERIA Unless noted in "Special Conditions or Instructions", the building being inspected was compared with a similar building. To the Consultant's knowledge the similar building used for comparison was constructed in accordance with generally accepted timber pest management practices and has since been maintained during all its life not to attract or support timber pest infestation.

Unless noted in "Special Conditions or Instructions", this Report assumes that the existing use of the building will continue.

This Report only records the observations and conclusions of the Consultant about the readily observable state of the property at the time of inspection. This Report therefore cannot deal with:

- (a) possible concealment of timber pest attack, including but not limited to, timber pest attack concealed by lack of accessibility, obstructions such as furniture, wall linings and floor coverings, or by applied finishes such as render and paint; and
- (b) undetectable or latent timber pest attack, including but not limited to, timber pest attack that may not be apparent at the time of inspection due to seasonal changes, recent or prevailing weather conditions, and whether or not services have been used some time prior to the inspection being carried out.

These matters outlined above in (a) & (b) are excluded from consideration in this Report.

If the Client has any doubt about the purpose, scope and acceptance criteria on which this Report was based please discuss your concerns with the Consultant on receipt of this Report.

The Client acknowledges that, unless stated otherwise, the Client as a matter of urgency should implement any recommendation or advice given in this Report.

LIMITATIONS

The Client acknowledges:

1. This Report does not include the inspection and assessment of matters outside the scope of the requested inspection and report.
2. The inspection only covered the Readily Accessible Areas of the Building and Site. The inspection did not include areas which were inaccessible, not readily accessible or obstructed at the time of inspection. Obstructions are defined as any condition or physical limitation which inhibits or prevents inspection and may include - but are not limited to - roofing, fixed ceilings, wall linings, floor coverings, fixtures, fittings, furniture, clothes, stored articles/materials, thermal insulation, sarking, pipe/duct work, builder's debris, vegetation, pavements or earth.
3. The detection of drywood termites may be extremely difficult due to the small size of the colonies. No warranty of absence of these termites is given.
4. European House Borer (*Hylotrupes bajulus*) attack is difficult to detect in the early stages of infestation as the galleries of boring larvae rarely break through the affected timber surface. No warranty of absence of these borers is given. Regular inspections including the carrying out of appropriate tests are required to help monitor susceptible timbers.
5. This is not a structural damage report. Neither is this a warranty as to the absence of Timber Pest Attack.
6. If the inspection was limited to any particular type(s) of timber pest (e.g. subterranean termites), then this would be the subject of a Special-Purpose Inspection Report, which is adequately specified.
7. This Report does not cover or deal with environmental risk assessment or biological risks not associated with Timber Pests (e.g. toxic mould) or occupational, health or safety issues. Such advice may be the subject of a Special-Purpose Inspection Report which is adequately specified and must be undertaken by an appropriately qualified inspector. The choice of such inspector is a matter for the Client.
8. This Report has been produced for the use of the Client. The Consultant or their firm or company are not liable for any reliance placed on this report by any third party.

EXCLUSIONS

The Client acknowledges that:

1. This Report does not deal with any timber pest preventative or treatment measures, or provide costs for the control, rectification or prevention of attack by timber pests. However, this additional information or advice may be the subject of a timber pest management proposal which is adequately specified.